



Aeroflex (MACOM Technology Solutions)

MACP-010507-CH0160

Numéro d'article:	MACP-010507-CH0160
Fabricant / marque:	Aeroflex (MACOM Technology Solutions)
Description du produit:	RF DIR COUPLER 5MHZ-300MHZ 5SMD
Feuilles de données:	MACP-010507-CH0160.pdf
Statut RoHS	Sans plomb / Conforme RoHS
Etat du stock	75562 pcs stock
Bateau de	Hong Kong
Manière d'expédition	DHL/Fedex/TNT/UPS/EMS

DEMANDE DE DEVIS

Solutions



L'image peut être une représentation. Voir les spécifications pour les détails du produit.

Spécifications de MACP-010507-CH0160

NUMÉRO D'ARTICLE	MACP-010507-CH0160
FABRICANT	Aeroflex (MACOM Technology Solutions)
LA DESCRIPTION	RF DIR COUPLER 5MHZ-300MHZ 5SMD
ÉTAT SANS PLOMB / ÉTAT ROHS	Sans plomb / Conforme RoHS
QUANTITÉ DISPONIBLE	75562 pcs
FICHE TECHNIQUE	MACP-010507-CH0160.pdf
PACKAGE COMPOSANT FOURNISSEUR	5-SMD
SÉRIES	-
PERTE DE RETOUR	31dB
PUISSANCE - MAX	500mW
EMBALLAGE	Tape & Reel (TR)
PACKAGE / BOÎTE	5-SMD Module
AUTRES NOMS	1465-1718-2
NIVEAU DE SENSIBILITÉ À L'HUMIDITÉ (MSL)	1 (Unlimited)
STATUT SANS PLOMB / STATUT ROHS	Lead free / RoHS Compliant
ISOLEMENT	-
PERTE D'INSERTION	0.4dB
LA FRÉQUENCE	5MHz ~ 300MHz
DESCRIPTION DÉTAILLÉE	RF Directional Coupler General Purpose 5MHz ~ 300MHz 17dB 500mW 5-SMD Module
FACTEUR DE COUPLAGE	17dB
TYPE COUPLER	Standard
APPLICATIONS	General Purpose

Tags associés

Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160	Distributeur MACP-010507-CH0160	MACP-010507-CH0160 Fournisseur
Prix MACP-010507-CH0160	MACP-010507-CH0160 Photos	Image MACP-010507-CH0160
MACP-010507-CH0160 PDF Fiche technique	MACP-010507-CH0160 Télécharger la fiche technique	MACP-010507-CH0160 Fiche technique
Action MACP-010507-CH0160	Acheter MACP-010507-CH0160	Acheter Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160
Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160	Aeroflex (MACOM Technology Solutions) Fournisseur	Distributeur Aeroflex (MACOM Technology Solutions)
Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160	Aeroflex Circuit Technology MACP-010507-CH0160	Aeroflex MACP-010507-CH0160
Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160	Aeroflex Metelics, Division of MACOM MACP-010507-CH0160	M/A-Com Technology Solutions MACP-010507-CH0160
Metelics (MACOM Technology Solutions) MACP-010507-CH0160	MACOM Technology Solutions MACP-010507-CH0160	

Produits connexes

<p>MACP-009730-C60370 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 5MHZ-1.2GHZ MOD En stock: 68058 pcs</p> <p>RFQ</p>	<p>MACP-010561-TR1000 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 2GHZ-6GHZ 6DFN En stock: 4662 pcs</p> <p>RFQ</p>
<p>MACP-010562-000000 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 6GHZ-18GHZ 6TDFN En stock: 4595 pcs</p> <p>RFQ</p>	<p>MACP-010414-CA0370 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD En stock: 103049 pcs</p> <p>RFQ</p>
<p>MACP-009596-CA01TB Fabricants: Aeroflex (MACOM Technology Solutions) La description: EVAL BOARD FOR MACP-009596-CA016 En stock: 485 pcs</p> <p>RFQ</p>	<p>MACP-009596-CA0160 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 5MHZ-1GHZ SM22 En stock: 27221 pcs</p> <p>RFQ</p>
<p>MACP-009011-C80370 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD En stock: 29238 pcs</p> <p>RFQ</p>	<p>MACP-010562-TR1000 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 6GHZ-18GHZ 6TDFN En stock: 3016 pcs</p> <p>RFQ</p>
<p>MACP-010250-C808A0 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 5MHZ-1.2GHZ MOD En stock: 114443 pcs</p> <p>RFQ</p>	<p>MACP-010562-001SMB Fabricants: Aeroflex (MACOM Technology Solutions) La description: EVAL BOARD FOR MACP-010562-TR100 En stock: 5017 pcs</p> <p>RFQ</p>
<p>MACP-010561-001SMB Fabricants: Aeroflex (MACOM Technology Solutions) La description: EVAL BOARD FOR MACP-010561-TR100 En stock: 3678 pcs</p> <p>RFQ</p>	<p>MACP-010561-000000 Fabricants: Aeroflex (MACOM Technology Solutions) La description: RF DIR COUPLER 2GHZ-6GHZ 6TDFN En stock: 4788 pcs</p> <p>RFQ</p>